

# PATTON ELECTRONICS

## Patton Electronics Company MATA Release Note v4.02.001\_0718 July 18 2006 10:47:46

### Table of Contents

1. Overview .....	0
2. Modification Requests Resolved .....	0

### 1. Overview

This document provides information on Modification Requests (MRs) resolutions in this product releases.

### 2. Modification Requests Resolved

Table1. AP Image MRs list

MR No.	Description	Version
20001	IP Fragmentation	4.02.001_0613
20002	Echo cancellation off (only in this release)	4.02.001_0629
20003	When you configure a fixed IP address, the M-ATA always sets the DNS to 80.0.0.1 unless the DNS field is blank	4.02.001_0709
20004	Change SI3215's LOOP CURRENT LIMIT from 20mA to 38mA.	4.02.001_0709
20005	M-ATA capable of opening TIP & RING momentarily when the Called Party hangs-up, then return Dial Tone like a normal POTS LINE	4.02.001_0718
20006	When you configure a fixed Ip address, the TA100 always sets the DNS to 80.0.0.1 unless the DNS field is blank	4.03.002_0730
20007	When config a fixed ip address and mask(no gateway,no dns) and reload the unit, then TA100 does not have dial-tone neither IVR access.	4.03.002_0730
20008	It take 2 minutes to head dial tone for problem #2 fix in the previous release	4.03.002_0802

Table 2. Downloader MRs list

MR No.	Description	Version
(blank)		